



© 1999 Drawings remain the property of Vental Australia Pty. Ltd.



## R80 RACK COUPLING - PLAN VIEW

Dwg. No. V30301

Rack arm coupling on a single mullion / glazing bar with double rack arm for blind join & 10mm gap between slat ends. This situation occurs when the opening width exceeds the maximum blind width requiring two or more individual blind units to be fitted side by side. Minimum space between rack arms on join 70mm.